



This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION TNC3200B-9214 JYE BAO CO., LTD. D **BODY** BRAID CLAMP GASKET WASHER NUT NUT DIAGRAM ASSEMBLY INSTRUCTION 14.6 [.575] Step 1: STRIP AS SHOWN. 7.5 [.296] Step 2: SLIDE BRAID CLAMP "B", GASKET "C", WASHER "D" AND NUT "E" OVER CABLE. Step 3: WRAP THE BRAIDING OVER "B". Step 4: STRIP AS SHOWN. Step 5: SLIDE PREPARED CABLE INTO CONNECTOR BODY "A" AND SCREW "E" ON THE BODY. SOLDER IN "Y". Step 7: FINALLY SCREW "F" ON THE CONNECTOR BODY "A".

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.