


HN3200-0058

HN Plug Clamp

50Ω



Parts	Material	Plating(Micro-inch)
Hex Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Washer	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Gasket	Silicon	
Braid Clamp	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Ferrule	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Pin	Brass	Silver 150 Over Copper 50
Insulator	Teflon	
Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Coupling Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50

Weight:









Suitable Cables: RG55, RG58, RG142, RG142-E, RG400

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

JYE BAO CO., LTD.

CABLE ASSEMBLY INSTRUCTION

HN3200-0058		DATE	2017/03/27	REV	—
A	B	C	D	E	F
					
BODY	CONTACT PIN	BRAID CLAMP	GASKET	WASHER	NUT
DIAGRAM		ASSEMBLY INSTRUCTION			
		Step 1: STRIP AS SHOWN.			
		Step 2: SLIDE NUT "F" 、 WASHER "E" 、 GASKET "D" AND BRAID CLAMP "C" OVER CABLE.			
		Step 3: WRAP THE BRAIDING OVER BRAID CLAMP "C" .			
		Step 4: STRIP AS SHOWN.			
		Step 6: PUT PIN "B" ON CENTER CONDUCTOR AND SOLDER IN "Y" .			
		Step 6: FINALLY SCREW NUT "F" ON THE CONNECTOR BODY "A" .			
This part number complies with RoHS. Notice: JYEBAO reserves the right to make modifications deemed appropriate.					
APPROVED		CHECKED		DRAWING	
				Albert	