



Parts	Material	Plating(Micro-inch)
Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Washer	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Gasket	Silicon	
Braid Clamp	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Coupling Nut	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Contact Pin	Brass	Gold 5 Over Nickel 50 Over Copper50
Insulator	Teflon	
Body	Brass	Tin-Zinc-Copper-Alloy 100 Over Copper 50

Weight: 112.6 g

Suitable Cables: RG214

This part numner complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION HN3200-9214 JYE BAO CO., LTD. C D E F Α В NUT **BODY** BRAID CLAMP GASKET WASHER NUT DIAGRAM ASSEMBLY INSTRUCTION Step 1: STRIP AS SHOWN. 28 [1.103] 7.2 [.284] Step 2: SLIDE BRAID CLAMP " C " ,GASKET " D " , WASHER " E " AND NUT " F " OVER CABLE . Step 3: WRAP THE BRAIDING OVER " C ". 33.8 [1.332] Step 4: STRIP AS SHOWN. Step 5: SCREW "F" ON THE CONNECTOR BODY "A". Step 6: SLIDE CENTER CONDUCTOR ON THE CONTACT PIN OF CONNECTOR "A " AND SOLDER IN "Y". Step 7: FINALLY SCREW "B" ON THE CONNECTOR BODY "A".

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.