

SMA3100-9L200 SMA Plug Crimp Right Angle 50Ω

8 HEX
(315 HEX)
1/4-36UNS
1/4

Parts	Material	Plating(Micro-inch)
Ferrule	Brass	Gold 5 Over Nickel 50 Over Copper 50
Cover	Brass	Gold 5 Over Nickel 50 Over Copper 50
Retainer Ring	Beryllium Copper	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Gasket	Silicon	
Contact Pin	Brass	Gold 20 Over Nickel 50 Over Copper 50
Insulator	Teflon	
Barrel	Brass	Gold 5 Over Nickel 50 Over Copper 50
Body	Brass	Gold 5 Over Nickel 50 Over Copper 50
Coupling Nut	Brass	Gold 5 Over Nickel 50 Over Copper 50

Weight:

Suitable Cables:JBY200

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION JYE BAO CO., LTD. SMA3100-9L200 **TAIPEI TAIWAN R.O.C** В С **BODY** COVER **FERRULE DIAGRAM** ASSEMBLY INSTRUCTION 13 [.512] Step 1: STRIP AS SHOWN. 5.1 [.201] 3.3 [.130] Step 2: SLIDE FERRULE " C " OVER CABLE. Step 3: WRAP THE BRAIDING UPWARDS. Step 4: SLIDE CENTER CONDUCTOR ON THE CONTACT PIN OF CONNECTOR "A " AND SOLDER IN " Y ". С Step 5: SLIDE FERRULE " C " TOWARDS THE CONNECTOR " A " AND CRIMP . **FORCE** Step 6: PRESS ON THE TOP OF "B" WITH JIGS. JIG

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.