



Weight: 31.1 g

Body

Coupling Nut

Suitable Cables: RG174, RG188, RG316, RG316-E,RG316-FEP

This part number complies with RoHS.

Brass

Brass

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

Tin-Zinc-Copper-Alloy 100 Over Copper 50

Tin-Zinc-Copper-Alloy 100 Over Copper 50



CABLE ASSEMBLY INSTRUCTION N3100-9316 JYE BAO CO., LTD. В Α С **FERRULE BODY** NUT ASSEMBLY INSTRUCTION DIAGRAM Step 1: STRIP AS SHOWN. 11.1 [.437] Step 2: SLIDE FERRULE "A" OVER CABLE. Step 3: WRAP THE BRAIDING UPWARDS. Step 4: SLIDE CENTER CONDUCTOR ON THE CONTACT PIN OF CONNECTOR "B" AND SOLDER IN "Y'. Step 5: SLIDE FERRULE "A" TOWARDS THE CONNECTOR "B" AND CRIMP. Step 6: SCREW "C" ON THE CONNECTOR.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.