





Parts	Material	Plating (Micro-inch)
i aits	iviateriai	Trating (Micro-incir)
Ferrule	Brass	Gold 5 Over Nickel 50 Over Copper 50
Contact Pin	Brass	Gold 20 Over Nickel 50 Over Copper 50
Renber Ring	Beryllium Copper	Tin-Zinc-Copper-Alloy 100 Over Copper 50
Gasket	Silicon	
Insulator	Teflon	
Body	Brass	Gold 5 Over Nickel 50 Over Copper 50
oupling Nut	Brass	Gold 5 Over Nickel 50 Over Copper 50

Weight: 3.00 g

Suitable Cables: RD316, RD316-FEP, RG316D-E, JBY100, RD316-LSFH

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION SMA3100D-0316 JYE BAO CO., LTD. В С FERRULE **BODY CONTACT PIN DIAGRAM** ASSEMBLY INSTRUCTION Step 1: STRIP AS SHOWN. 2.5 [.098] В Step 2: SLIDE FERRULE "A" OVER CABLE. Step 3: PUT PIN "B" ON CENTER CONDUCTOR AND SOLDER IN "Y". Step 4: LOOSEN BRAIDING AND SLIDE CONNECTOR "C" IN PLACE. Step 5: SLIDE FERRULE "A" TOWARDS THE CONNECTOR "C" AND CRIMP.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.