



Weight: 22.14 g

Suitable Cables: RG58, JBY195

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION TNC3100-9058 JYE BAO CO., LTD. В С BODY NUT **FERRULE** DIAGRAM ASSEMBLY INSTRUCTION Step 1: STRIP AS SHOWN. 11 [.433] 3.8 [.150] Step 2: SLIDE FERRULE " C " OVER CABLE . Step 3: WRAP THE BRAIDING UPWARDS. Step 4: SLIDE CENTER CONDUCTOR ON THE CONTACT PIN OF CONNECTOR " A " AND SOLDER IN "Y" Step 5: SLIDE FERRULE " C " TOWARDS THE CONNECTOR " A " AND CRIMP $\ .$ Step 6: FINALLY SCREW NUT " B " ON THE CONNECTOR BODY "A".

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.