





Parts	Material	Plating(Micro-inch)
Ferrule	Brass	Gold 5 Over Nickel 50 Over Copper 50
Cover	Brass	Gold 5 Over Nickel 50 Over Copper 50
Coupling Nut	Brass	Gold 5 Over Nickel 50 Over Copper 50
Renber Ring	Beryllium Copper	Gold 5 Over Nickel 50 Over Copper 50
Contact Pin	Beryllium Copper	Gold 20 Over Nickel 50 Over Copper 50
Insulator	Teflon	
Body	Brass	Gold 5 Over Nickel 50 Over Copper 50

Weight: 1.82 g

Suitable Cables: RG174, RG188, RG316, RG316-E, RG316-FEP

This Part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION SSMB3100-9316 JYE BAO CO., LTD. Α В С **BODY** COVER **FERRULE** DIAGRAM ASSEMBLY INSTRUCTION Step 1: STRIP AS SHOWN. 3.05 [.120] 2 [.079] Step 2: SLIDE FERRULE " C " OVER CABLE . Step 3: WRAP THE BRAIDING UPWARDS. С Step 4: SLIDE CENTER CONDUCTOR ON THE CONTACT PIN OF CONNECTOR " A " AND SOLDER IN "Y" Step 5: SLIDE FERRULE " C " TOWARDS THE CONNECTOR " A " AND CRIMP . Step 6: PRESS ON THE TOP OF "B" WITH JIGS. JIG FORCE

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.