



Weight: 4.22 g

Suitable Cables: RG58, JBY195

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.

## JYE BAO CO., LTD. CABLE ASSEMBLY INSTRUCTION

	: ASSEMBL		1	DEV.		
SMB3100-0058	5	DATE	2017/03/27	REV	_	
А	E	3	С			
	<b>=</b> -#	<b>⊒</b> •				
BODY	CONTA	ACT PIN	FERRU	FERRULE		
DIAGRAM			ASSEMBLY INSTRUCTION			
8	12.3	Step 1: STRIP AS	S SHOWN.			
C C	Step 2: SLIDE FERRULE " C " OVER CABLE. Step 3: PUT PIN " B " ON CENTER CONDUCTOR AND SOLDER OR CRIMP IN " Y ". (USE SQUARE 0.98mm/0.039inch SECTION OF INSERT-B IF CRIMPED)					
		Step 4: LOOSEN	BRAIDING AND SLIDE CO	NNECTOR " A '	' IN PLACE.	
C		Step 5: SLIDE FERRULE " C " TOWARDS THE CONNECTOR " A " AND CRIMP. (USE 5.5mm/0.217inch HEX SECTION OF INSERT-B)				
This part number complies with RoHS.						
Notice: JYEBAO reserves the right to make modifications deemed appropriate.						
APPROVED	CHECKED		DRAWING	Albert		
					_	