





Parts	Material	Plating (Micro-inch)
Ferrule	Brass	Gold 5 Over Nickel 50 Over Copper 50
Contact Pin	Brass	Gold 20 Over Nickel 50 Over Copper 50
Renber Ring	Beryllium Copper	Gold 5 Over Nickel 50 Over Copper 50
Barrel	Brass	Gold 5 Over Nickel 50 Over Copper 50
Insulator	Teflon	
Body	Brass	Gold 5 Over Nickel 50 Over Copper 50

Weight: 0.76 g

Suitable Cables: RG174, RG188, RG316,RG316-E, RG316-FEP

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.



CABLE ASSEMBLY INSTRUCTION MMCX3100-0316 JYE BAO CO., LTD. В Ε FERRULE BODY CONTACT PIN *TOOLS AND FIXTURES ARE REFERENCE ON PAGE 306 OF JYEBAO'S 2005 CATALOG. DIAGRAM ASSEMBLY INSTRUCTION Step 1: STRIP AS SHOWN . 4.3 [.169] Step 2: SLIDE FERRULE "B" OVER CABLE. Step 3: PUT PIN " E " ON CENTER CONDUCTOR AND SOLDER IN " Y ". Step 4: LOOSEN BRAIDING AND SLIDE CONNEC TOR "A" IN PLACE. Step 5: SLIDE FERRULE "B" TOWARDS THE CONNECTOR " A " AND CRIMP.

This part number complies with RoHS.

Notice: JYEBAO reserves the right to make modifications deemed appropriate.